



## Digital 6000

### L 6000 - Firmware version 3.0.1

For conformity, consistency and compatibility reasons, we strongly recommend upgrading the L 6000 to the new release.

### Features

- Support of LM 6070 charging module for BA 70 rechargeable battery pack.

### Notes

- No “time to empty” parameter in WSM for BA 70 rechargeable battery pack is supported.

### Firmware update

- The L 6000 firmware update requires the Sennheiser Wireless Systems Manager software:  
[www.sennheiser.com/wsm](http://www.sennheiser.com/wsm)



## **Previous Releases**

### **L 6000 Firmware version 2.0.12**

#### **Features**

- Bug fixes and optimizations

### **L 6000 - Firmware version 2.0.11**

#### **Features**

- Improved charging behavior for BA 62
- Bug fixes and optimizations

### **L 6000 - Firmware version 2.0.10**

#### **Features**

- BA 62: Missing “time to full” parameter in WSM implemented
- Bug fixes and optimizations

### **L 6000 - Firmware version 2.0.8**

#### **Features**

- Support of LM 6062 charging module for BA 62 rechargeable battery pack
- Bug fixes and optimizations

#### **Known issues**

- No “time to full” parameter in WSM for BA 62 rechargeable battery pack

### **L 6000 - Firmware version 1.2.1**

#### **Features**

- Problem with phantom error messages concerning the fan system has been resolved.